






A vertical number line with major tick marks at 0, 10, 20, 30, 40, 50, 60, 70, 80, 90, and 100. The numbers are written to the left of the line.

ACABAMENTO DE SUPERFÍCIE	
DIN 1302	DIN 3141
$\sqrt{Rz1}$	
$\sqrt{Rz4}$	
$\sqrt{Rz16}$	
$\sqrt{Rz63}$	
 M.Bruto	

desenhado em NX